

CHANGE HISTORY for

- ✓ **AVIC-F40BT**
- ✓ **AVIC-F940BT**
- ✓ **AVIC-F840BT**
- ✓ **AVIC-F8430BT**

Ver 05.100

- ✓ Support for iPhone 5 and fifth generation iPod touch.

Remarks

- iPhone 5 compatibility requires the purchase of Pioneer CD-IV202NAVI interface cable kit, Apple® Lightning to VGA Adapter, and Apple USB to Lightning cable (each sold separately).
- No need to install this update if you do not own an iPhone 5 or fifth generation iPod touch.

Ver 04.010000

- ✓ The new firmware improves the following issues:
 - AHA performance (display speed) through Bluetooth connection
 - Unit cannot calculate fuel costs on beforehand in Norwegian currency
 - "Advanced App Mode" positioning (NavGate Drive will reroute less often)