

CHANGE HISTORY for

- ✓ **AVIC-F20BT**
- ✓ **AVIC-F920BT**
- ✓ **AVIC-F9210BT**
- ✓ **AVIC-F9220BT**

Ver 2.00300

The new firmware fixes the following issues:

- ✓ Contacts are transferred backwards
- ✓ Voice Recognition / BT Activation Process
- ✓ Unit switches off when USB is connected
- ✓ Incorrect Spanish translation for BT message "Connection successful"