

CHANGE HISTORY for

AVH-Z5100DAB

AVH-Z5100BT

AVH-Z3100DAB

AVH-Z2100BT

AVH-Z1100DVD

Ver 8.15 / 18.15 (February, 2020 Update)

- ✓ Fixed the problem that there is no sound from the rear speakers after finishing a call.

Ver 8.12 (June, 2019 Update)

- ✓ Improved touch accuracy of external navigation system.
- ✓ Minor bug fixes

Ver 8.11 (December, 2018 Update)

- ✓ Improved behavior when connecting with smartphone device

Ver 8.10 (July, 2018 Update)

- ✓ Fixes the following problem
 - Artwork is displayed with a delay of one song at iPod source, when an iPod or iPhone with iOS version 11.3 is connected.

Ver 8.07 (April, 2018 Update)

- ✓ Fixes the following problems
 - The shown name is wrong in Bluetooth phone book if name has a blank.
 - Sometimes the touch response is slow in AppRadio Mode
 - the play back tempo of BT-Audio is delayed on certain BT devices.
 - Other minor problems.
- ✓ Changed the picture changing method of "Changing the wide screen mode" setting as follows.
 - You can display images across the entire screen in [Full] mode.
(Some images may not be displayed across the entire screen.)
 - You can display images without changing the ratio in [Normal] mode.