

## CHANGE HISTORY for

- ✓ **AVH-X5800BT**
- ✓ **AVH-X5800DAB**
- ✓ **AVH-X4800DVD**
- ✓ **AVH-X3800DAB**
- ✓ **AVH-X2800BT**
- ✓ **AVH-X1800DVD**

### Remarks:

- ✓ **Make sure to download the correct firmware file for your region, the European versions (EW or UW model) and US version (\*) use a different update file**  
(\* ) In case you have US model, please visit '[pioneerelectronics.com/firmware](http://pioneerelectronics.com/firmware)'
- ✓ **Do NOT install a firmware file which is intended for a different region.**

### Ver 8.22 (January, 2019 Update)

- ✓ Corrects a problem in the iPod source where the artwork does not change to match the current track.
- ✓ Corrects a problem with the voice recognition operation via the steering wheel controls.
- ✓ Corrects a problem in iPod source where a track may be skipped when "Short Playback Mode" of MIXTRAX settings is turned on

### Ver 8.18 (July, 2016 Update)

- ✓ Add "AppRadioMode Sound" setting to the System Menu (\*)
- ✓ DAB Models only: Fixed the issue of some particular characters on DAB screen

(\* ) The AppRadioMode Sound setting can be used to define if the AppradioMode sound should be output from the speakers connected to the AVH product or direct from the Android phone speaker.

### Remarks:

- The setting has been implemented as some Android phones cannot output the AppRadioMode sound.
- With an iPhone, the sound is always output from the speakers connected to the unit.
- The setting is available from System settings → Input/Output setting → AppRadioMode sound → AVH/Smartphone)