

CHANGE HISTORY for

- ✓ **DEH-S5000BT**
- ✓ **DEH-S4000BT**
- ✓ **DEH-S040BT**
- ✓ **DEH-S3000BT**
- ✓ **MVH-S300BT**
- ✓ **MVH-S030BT**

Remarks:

- ✓ **Make sure to download the correct firmware file for your region, the European versions (EW or UW model) and US version (*) use a different update file**
(*) In case you have US model, please visit 'pioneerelectronics.com/firmware'
- ✓ **Do NOT install a firmware file which is intended for a different model and or region.**

Ver 8.15 (August, 2018 Update)

- ✓ Fixed the problem that the receiving volume of particular smart phone becomes low when talking on the phone connected to a CD Receiver with BT.
- ✓ Fixed the problem that USB source playback will stop when the ID3 tag contains specific genre number information.
- ✓ Fixed the problem that the phone number will not be displayed on a CD Receiver when a contact information in a phone's address book contains a photo/image.
- ✓ Supports Bluetooth playback of some smart phones (Android Ver. 8).