

SPH-DA130DAB - CHANGE HISTORY

Ver 8.10 (February, 2020 Update)

- ✓ Fixed the problem that there is no sound from the rear speakers after finishing a call.

Ver 8.09 (June, 2019 Update)

- ✓ Improved touch accuracy of external navigation system.
- ✓ Minor bug fixes

Ver 8.08 (December, 2018 Update)

- ✓ Improved behavior when connecting with smartphone device

Ver 8.07 (July, 2018 Update)

- ✓ Fixes the problem that the artwork is displayed with a delay of one song at iPod source, when an iPod or iPhone with iOS version 11.3 is connected.

Ver 8.05 (April, 2018 Update)

- ✓ Fixes the following problems
 - The shown name is wrong in Bluetooth phone book if name has a blank.
 - Sometimes the touch response is slow in AppRadio Mode
 - the play back tempo of BT-Audio is delayed on certain BT devices.
 - "TA Interrupt" of Radio settings can be registered to Favorite menu (AVH-Z2000BT Only)
 - Other minor problems.
- ✓ Changed the picture changing method of "Changing the wide screen mode" setting as follows.
 - You can display images across the entire screen in [Full] mode.
(Some images may not be displayed across the entire screen.)
 - You can display images without changing the ratio in [Normal] mode.

Ver 8.04 (January, 2018 Update)

- ✓ Fixes a problem that the order of your surname & first name appears incorrectly if you put a space between surname & first name in Bluetooth phone book
- ✓ Fixes a problem that touch screen's response speed becomes slow sometimes for AppRadio Mode.
- ✓ Fixes a problem that the rhythm tempo of BT-Audio becomes slower than original music in case of certain devices.
- ✓ Revised the announcement for screen aspect ratio modes (Full & Normal)
- ✓ Improved other minor problems.