

## **AVH-X3500DAB - CHANGE HISTORY**

### **SEPTEMBER 2013 UPDATE**

- ✓ Correction for German message "Aisplay Aus" into "Display Aus"
- ✓ Improvement of the DAB Antenna power detection to prevent that an antenna error is generated when there is a temporary battery voltage drop which might occur on cars equipped with Start/Stop technology.

### **MARCH 2013 UPDATE**

- ✓ Support for iPhone 5 and fifth generation iPod touch.

#### **Remarks**

- iPhone 5 compatibility requires the purchase of Pioneer CD-IV202AV interface cable kit, Apple® Lightning to VGA Adapter, and Apple USB to Lightning cable (each sold separately).