



CHANGE HISTORY FOR SPH-EVO107DAB, SPH-EVO98DAB and SPH-DA97DAB

Ver 3.00 (July, 2026 Update)

- ✓ Fixed an audio issue that occurred when switching tracks during music playback in CarPlay.
- ✓ Improved smartphone connectivity.
- ✓ Added a function to switch the display between the Rear-View Camera and 2nd Camera.
- ✓ Minor bug fixes

Ver 2.00 (January, 2026 Update)

- ✓ Improved the usability of the radio preset channel list.
- ✓ Minor bug fixes.

Ver 1.70 (November, 2025 Update)

- ✓ Improved audio start time after selecting a DAB station; reducing delays caused by certain broadcasts.

Ver 1.600200 (May, 2025 Update)

- ✓ Minor bug fixes.

Ver 1.0403 (January, 2025 Update)

- ✓ Fixed an issue with AAC format audio file playback when using USB Audio Source
- ✓ Minor bug fixes.