

CHANGE HISTORY for

✓ SPH-10BT

Ver 8.27 (January, 2022 Update)

- ✓ Addresses an issue where Bluetooth device pairing information cannot be retrieved.
- ✓ Improved Bluetooth Pairing.
- ✓ Minor improvements.

Ver 8.21 (August, 2020 Update)

- ✓ Fixed a BT connection issue.
- ✓ Minor improvements

Ver 8.18 (July, 2019 Update)

- ✓ Fixed a BT connection issue.
- ✓ Minor improvements

Ver 8.17 (April, 2019 Update)

- ✓ Fixed a BT pairing issue.
- ✓ Fixed an issue that iPhone icon is missing
- ✓ Add compatibility to ADAS app